# Oil Field Environmental Incident Summary

**Responsible Party:** MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: VIRGINIA LEIGH 33-28H

Field Name: MIDWAY Well File #: 19672

Date Incident: 12/2/2014 Time Incident: 10:00 Facility ID Number:

County: WILLIAMS Twp: 157 Rna: 95 Sec: 33 Qtr: SE SE

**Location Description:** 

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 1000 Feet

Distance Nearest Water Well: Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 30 Gallons 25 Gallons

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/13/2016 Clean Up Concluded: 10/6/2015

Risk Evaluation:

None

Areal Extent:

approximately 300 feet of oil mist into the field

## Potential Environmental Impacts:

None

#### Action Taken or Planned:

Contaminated snow being cleaned up. Area will be monitored for remediation if necessary.

Wastes Disposal Location: Prairie Disposal

Agencies Involved:

## **Updates**

Date: 12/3/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Treater popoff sprayed crude oil off location into a field. Followup is necessary.

Date: 12/4/2014 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

12/4/2014 at 13:33, on location. Met with report contact. Personnel currently loading impacted snow/dirt into sidedump with a front loader. Spray came out of flare pit in a fan shape, roughly due north to due east, with the furthest impact being noted in a northeasterly direction. Some impacted snow still visible. Met with report contact and pointed out the spots, primarily due north and right along the treeline to the northeast. There is another spill currently being cleaned up by the company. Once that cleanup is complete, equipment will be moved back to this site to finish up.

Date: 4/21/2015 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

4/21/2015 at 15:11, on location. Field has been further scraped up to north and northeast of flare, and there is no remaining staining visible. No visible staining on unscraped vegetation/tree row further to northeast.